

catoolRT 15.9 Release Notes

Changes since 15.6:

- Add logging of CAN signals at cycle rate
- CAN AK protocol address now configurable
- Improvements to diagram update rate
- Configure whether CDM counter mismatch will cause re-sync
- Add knock boss analysis
- Add crank and cam filtering for encoderless operation
- Add splash screen for reseller licences
- Improve support for camshaft synchronised acquisition
- Add "Reload Acquisition" to reload data into the DAQ data source
- Improve status messages during DAQ
- Option to show update rate in diagrams
- Ensure TDC trigger location cannot be configured in an invalid position