

## catoolRT 18.3 Release Notes

Changes since 17.12:

- Enable XCP protocol support for TCP and UDP (Ethernet) transports – CANbus transport is not yet fully functional
- Enable AK protocol support for TCP (Ethernet)
- Add “DAQ Status” to parameters
- Improvements to screen update rate
- Speed improvements to “Data List” update rate
- Fix CANbus message unpacking
- Move to wxWidgets 3.1.1 library
- Fix crash when loading Alarm configurations
- Add status messages when exiting application
- Don't test for an alarm condition if there are no triggers
- Improve alarm detection during buffer wraparound
- Calculate statistics if a Data list item or XCP item is added whilst a DAQ is in progress
- Don't move message box when new items added
- Fixes to low speed logging
- Add “CANbus Input” and “XCP Status” to Acquisition Information (File -> Properties)